

EISA Token Ring Release Notes

HP 9000 Networking



**Manufacturing Part Number: J2165-90046
E1201**

United States

© Copyright 2001 Hewlett-Packard Company.

Legal Notices

The information in this document is subject to change without notice.

Hewlett-Packard makes no warranty of any kind with regard to this manual, including, but not limited to, the implied warranties of merchantability and fitness for a particular purpose. Hewlett-Packard shall not be held liable for errors contained herein or direct, indirect, special, incidental or consequential damages in connection with the furnishing, performance, or use of this material.

Warranty. A copy of the specific warranty terms applicable to your Hewlett-Packard product and replacement parts can be obtained from your local Sales and Service Office.

Restricted Rights Legend. Use, duplication or disclosure by the U.S. Government is subject to restrictions as set forth in subparagraph (c) (1) (ii) of the Rights in Technical Data and Computer Software clause at DFARS 252.227-7013 for DOD agencies, and subparagraphs (c) (1) and (c) (2) of the Commercial Computer Software Restricted Rights clause at FAR 52.227-19 for other agencies.

HEWLETT-PACKARD COMPANY
3000 Hanover Street
Palo Alto, California 94304
U.S.A.

Use of this manual and flexible disk(s) or tape cartridge(s) supplied for this pack is restricted to this product only. Additional copies of the programs may be made for security and back-up purposes only. Resale of the programs in their present form or with alterations, is expressly prohibited.

Copyright Notices. ©copyright 1983-2001 Hewlett-Packard Company, all rights reserved.

Reproduction, adaptation, or translation of this document without prior written permission is prohibited, except as allowed under the copyright laws.

©copyright 1979, 1980, 1983, 1985-93 Regents of the University of California

This software is based in part on the Fourth Berkeley Software Distribution under license from the Regents of the University of California.

©copyright 1980, 1984, 1986 Novell, Inc.

©copyright 1986-1992 Sun Microsystems, Inc.

©copyright 1985-86, 1988 Massachusetts Institute of Technology. ©copyright 1989-93 The Open Software Foundation, Inc.

©copyright 1986 Digital Equipment Corporation.

©copyright 1990 Motorola, Inc.

©copyright 1990, 1991, 1992 Cornell University
©copyright 1989-1991 The University of Maryland
©copyright 1988 Carnegie Mellon University

Trademark Notices UNIX is a registered trademark of The Open Group.

X Window System is a trademark of the Massachusetts Institute of Technology.

MS-DOS and Microsoft are U.S. registered trademarks of Microsoft Corporation.

OSF/Motif is a trademark of the Open Software Foundation, Inc. in the U.S. and other countries.

EISA Token Ring Release Notes for HP-UX 11.0

The following information is for EISA Token Ring LAN adapters on HP-UX version 11.00.

What's in this Version

The following describes the EISA Token Ring products for the D-Class/R-Class servers and the B, C, and J-Class and series 700 workstations with an EISA backplane.

Fixes

This version of the product contains fixes for recent defects and defects listed in PHNE_17942.

Known Problems and Workarounds

None

Compatibility Information and Installation Requirements

Software Requirements

- HP-UX 11.0 operating system

The multicast feature of the EISA Token Ring product depends on DLPI patch PHNE_25395; however, the product is installable and functions without this patch.

Hardware Requirements

- D-Class/R-Class servers and the B, C, and J-Class and series 700 workstations with an EISA backplane
- CD-ROM drive

Memory and Disk Space Requirements

- 16 MB memory
- 500 KB free disk space

Install/Upgrade With System Up or Down

- Install the EISA Token Ring card with the system down.
- One reboot is required for installation and configuration.

Installing and Upgrading EISA Token Ring

The EISA Token Ring card is customer-installable and configurable on D-Class/R-Class servers and B, C, and J-Class and Series 700 workstations with an EISA back plane.

Patches and Fixes for this Version (B.11.00.07)

Fixes:

- **EISA Token Ring causes a system panic at regular intervals.**
This problem is fixed by correcting cache flush/purge size.
- **EISA Token Ring fails to detect a cable disconnect.**
The driver code is not sending linkdown and linkup events during cable disconnect/reconnect.
The driver code has been modified to send linkup and linkdown events in the cable disconnect/reconnect path.
- **The lanadmin reset causes a system panic with the cable disconnected.**
The driver lock is being held before sending linkup event in the reset path.
The driver code has been modified to release a driver lock before sending a linkup event in the reset path.
- **DLPI multicast enable/disable fails on EISA Token Ring due to the problem in the implementation of the DLPI multicast.**
The driver code has been modified to support both DLPI multicast enable/disable.
- **IP multicast does not work under certain conditions because it is not properly implemented on EISA Token Ring.**
The driver code has been modified to support IP multicast enable/disable.

Patch PHNE_17942:

- **lanadmin reports card down when it's not.**
A code change in the EISA Token Ring initialization function has fixed this defect.
- **Connecting the EISA Token Ring card causes a system crash.**
The driver software has been changed to check for physically contiguous space returned by MALLOC. MALLOC is re-tried up to 100 times to prevent a system hang. If this is exceeded, the card is kept in the down state.
- **'snmpwalk' shows inconsistent values.**
The driver software has been modified to call get_nmid() only once per instance.
- **When an EISA Token Ring card is used with other Token Ring cards supporting**

4500 MTU size, the network may hang.

The maximum MTU size for EISA Token Ring has been increased to 4500. The default MTU is now set to 4170. The user may increase this up to 4500 using the `lanadmin` command, if desired.

- **SAM gives an error when configuring the EISA Token Ring card.**

The initialization script has been modified to use the correct syntax for the shell command.

- **The “swverify(1M)” command will try to verify control scripts such as “configure”, “verify”, “postinstall” and “checkinstall” for ownership and permissions. Since these are control scripts, “swverify(1M)” should not perform this check on them.**

This defect has been fixed.