

# Compaq DRTape Compatibility Matrix

April 2001

Compaq Server		ProLiant DL 380: Bios P21 or higher	ProLiant DL 380: Bios P17 or higher	ProLiant DL 580: Bios P20 or higher	ProLiant ML 350: Bios P02 or higher	ProLiant ML 370: Bios P17 or higher	ProLiant ML 550: Bios P19 or higher	ProLiant ML 570: Bios P20 or higher	ProLiant PL 1600: Bios P08 or higher	ProLiant PL 1850R: Bios P07 or higher	ProLiant PL 5500: Bios P12 or higher:	ProLiant PL 6400R: Bios P11 or higher	ProLiant PL 7000: Bios P40 / P43	ProLiant PL 8000: Bios P41 or higher			
Operating System		WinNT 4.0 **	WinNT 4.0 **	WinNT 4.0 **	WinNT 4.0 **	WinNT 4.0 **	WinNT 4.0 **	WinNT 4.0 **	WinNT 4.0 **	WinNT 4.0 **	WinNT 4.0 **	WinNT 4.0 **	WinNT 4.0 **	WinNT 4.0 **	Service Pack 5 or higher must be installed with WinNT 4.0		
Backup Application		VERITAS 8.5	VERITAS 8.5	VERITAS 8.5	VERITAS 8.5	VERITAS 8.5	VERITAS 8.5	VERITAS 8.5	VERITAS 8.5	VERITAS 8.5	VERITAS 8.5	VERITAS 8.5	VERITAS 8.5	VERITAS 8.5	Minimum Drive Firmware Rev.		
<b>Controller</b>	Ultra 2 SCSI 64-bit 34875-B21	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	AIT 35GB	4.16	
		1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	AIT 50GB	1.30
		1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	AIT 35GB LVD	3.07
		1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	DAT 20/40GB	1.12
	Ultra Wide SCSI 3 Adapt 272514-001	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	AIT 35GB	4.16
		1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	AIT 50GB	1.30
		1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	AIT 35GB LVD	3.07
		1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	1,3	DAT 20/40GB	1.12
	Symbios Embedded NOTE: The ROC module cannot be installed when using the DRTape Backup Solution	1	1	1	1	1	4	1	1	1	1	1	1	1	1	AIT 35GB	4.16
		1	1	1	1	1	4	1	1	1	1	1	1	1	1	AIT 50GB	1.30
		1	1	1	1	1	4	1	1	1	1	1	1	1	1	AIT 35GB LVD	3.07
		1	1	1	1	1	4	1	1	1	1	1	1	1	1	DAT 12/24GB	4.20
		1	1	1	1	1	4	1	1	1	1	1	1	1	1	DAT 20/40GB	1.12
		2	2	2	2	2	4	2	2	2	2	2	2	2	2	DAT 12/24GB AutoLoader	2.13
	Ultra 3 S/Channel HBA 154457-B21 Bios 3.01.2	1	1	1	1	1	1	1	1	1	1	1	1	1	1	AIT 35GB	4.16
		1	1	1	1	1	1	1	1	1	1	1	1	1	1	AIT 50GB	1.30
		1	1	1	1	1	1	1	1	1	1	1	1	1	1	AIT 35GB LVD	3.07
		1	1	1	1	1	1	1	1	1	1	1	1	1	1	DAT 12/24GB	4.20
		1	1	1	1	1	1	1	1	1	1	1	1	1	1	DAT 20/40GB	1.12
		2	2	2	2	2	2	2	2	2	2	2	2	2	2	DAT 12/24GB AutoLoader	2.13
		2	2	2	2	2	2	2	2	2	2	2	2	2	2	DAT 20/40GB AutoLoader	5.06
	1	1	1	1	1	1	1	1	1	1	1	1	1	1	SDLT	V-15-19	
	Ultra 3 D/Channel HBA 129803 B21 Bios 3.01.2	1	1	1	1	1	1	1	1	1	1	1	1	1	1	AIT 35GB	4.16
		1	1	1	1	1	1	1	1	1	1	1	1	1	1	AIT 50GB	1.30
		1	1	1	1	1	1	1	1	1	1	1	1	1	1	AIT 35GB LVD	3.07
		1	1	1	1	1	1	1	1	1	1	1	1	1	1	DAT 12/24GB	4.20
		1	1	1	1	1	1	1	1	1	1	1	1	1	1	DAT 20/40GB	1.12
		2	2	2	2	2	2	2	2	2	2	2	2	2	2	DAT 12/24GB AutoLoader	2.13
2		2	2	2	2	2	2	2	2	2	2	2	2	2	DAT 20/40GB AutoLoader	5.06	
1	1	1	1	1	1	1	1	1	1	1	1	1	1	SDLT	V-15-19		

Supported Tape Drive Models (Internal and External)

- 1 - Requires SmartStart 4.9 or higher.
- 2 - Install SoftPaq # 14476 which corrects an AutoLoader Driver problem in SmartStart 4.9.
- 3 - Controller must be on the Primary PCI BUS.
- 4 - The DRTape Backup Solution is not supported with this server and tape drive configuration.