

Smart Array 5i and 532 version 2.62

This Smart Array firmware will recommend updates for some SCSI disk drive models after the Smart Array firmware has been installed. To avoid notification during the POST routine, update any applicable hard disk drives before updating the Smart Array firmware.

Disk drive firmware components are available from:

http://h18000.www1.hp.com/support/files/storage/us/locOsCat/99_56.html

If a component is not available for the affected disk drive model, download the following ROMPaq:

<http://h18000.www1.hp.com/support/files/server/us/download/17149.html>

A later version of the disk drive firmware may be available and should be used.

Disk Drive Model	Minimum Firmware	Disk Drive Family
AB009335B8	A019	SCSI 9GB 7200 WU
AB018335B9	A019	SCSI 18GB 7200 WU
AD00435332	A415	SCSI 4GB 10K WU
AD009335C9	A018	SCSI 9GB 10K WU
AD00935335	A915	SCSI 9GB 10K WU
AD018335CA	A018	SCSI 18GB 10K WU
AD018345A6	A011	SCSI 18GB 10K WU
BB009135B4	B021	SCSI 9GB 7200 WU2
BB009235B6	B021	SCSI 9GB 7200 WU2
BB018135B5	B021	SCSI 18GB 7200 WU2
BB018235B7	B021	SCSI 18GB 7200 WU2
BD004153C3	B415	SCSI 4GB 10K WU2
BD004253C4	B415	SCSI 4GB 10K WU2
BD00962A66	B008	SCSI 9GB 10K WU3
BD0096349A	3B12	SCSI 9GB 10K WU3
BD009635C3	B022	SCSI 9GB 10K WU3
BD00965333	B915	SCSI 9GB 10K WU3
BD00972A69	B008	SCSI 9GB 10K WU3
BD009735C6	B022	SCSI 9GB 10K WU3
BD00975334	B915	SCSI 9GB 10K WU3
BD01862A67	B008	SCSI 18GB 10K WU3
BD0186349B	3B12	SCSI 18GB 10K WU3
BD018635C4	B022	SCSI 18GB 10K WU3
BD0186459A	B011	SCSI 18GB 10K WU3
BD01872A6A	B008	SCSI 18GB 10K WU3
BD018735C7	B022	SCSI 18GB 10K WU3
BD018745A3	B011	SCSI 18GB 10K WU3
BD036635C5	B022	SCSI 36GB 10K WU3
BD0366459B	B011	SCSI 36GB 10K WU3
BD036735C8	B022	SCSI 36GB 10K WU3
BD036745A4	B011	SCSI 36GB 10K WU3
BD0726459C	B011	SCSI 72GB 10K WU3
BD07287B4C	HPB5	SCSI 72GB 10K U320
BD07297B57	HPB5	SCSI 72GB 10K U320
BD14687B52	HPB5	SCSI 146GB 10K U320
BD14697B58	HPB5	SCSI 146GB 10K U320
BD30087B53	HPB5	SCSI 300GB 10K U320
BF01865222	B009	SCSI 18GB 15K WU3
BF03665223	B009	SCSI 36GB 15K WU3

Smart Array 5i and 532 version 2.62 (continued from previous page)

Disk Drive Model	Minimum Firmware	Disk Drive Family
BF03687B54	HPB1	SCSI 36GB 15K U320
BF03697B5A	HPB1	SCSI 36GB 15K U320
BF07287B55	HPB1	SCSI 72GB 15K U320
BF07297B5B	HPB1	SCSI 72GB 15K U320
BF14687B56	HPB1	SCSI 146GB 15K U320
BF14697B5C	HPB1	SCSI 146GB 15K U320
DGHS09U	01C0	SCSI 9GB 7200 WU
DGHS09Y	01C0	SCSI 9GB 7200 WU
DGHS18Y	01C0	SCSI 18GB 7200 WU
ST19171	9A10	SCSI 9GB 7200 WU