

StorageWorks ESL9322S2 Library Configuration Guide

ESL9322 library with SDLT 160/320 drives

293409-B22	ESL9322S2 222 slot 2 SDLT 160/320 drives
293409-B28	ESL9322S2 222 slot 8 SDLT 160/320 drives
293410-B22	ESL9322S2 322 slot 2 SDLT 160/320 drives
293410-B28	ESL9322S2 32 2slot 8 SDLT 160/320 drives

Add-on drive supported

293414-B21	ESL9000 Add-on SDLT 320 drive
------------	-------------------------------

Power Cords Supported

146210-001	ESL9000 Power cords pair, US/CANADA/MEX* <i>*(shipped with all units)</i>
146210-AR1	ESL9000 Power cord pair, SE ASIA/INDIA
146210-021	ESL9000 Power cord pair, CENTRAL EUROPE
146210-011	ESL9000 Power cord pair, AUS/CHINA/NZL
146210-111	ESL9000 Power cord pair, SWITZERLAND
146210-031	ESL9000 Power cord pair, UK/HONG KONG
146210-061	ESL9000 Power cord pair, ITALY
146210-081	ESL9000 Power cord pair, DENMARK
146210-291	ESL9000 Power cord pair, JAPAN

NOTE: Order Local power cords separately, supplied from regions

DAS connection: Controllers supported

ProLiant Servers

129803-B21 Dual channel WU 3 SCSI controller

154457-B21 Single channel WU 3 SCSI controller

Alpha Servers

3X-KZPCA-AA Single Channel Ultra 2 Controller

SAN connection: FC to SCSI routers supported

262653-B21 Network Storage Router m2402 (2FC X 4 LVD SCSI)

262665-B21 Embedded Data Router, ESL 9000 embedded fibre option e2400 – Base

262664-B21 Embedded Data Router, ESL 9000 embedded fibre option e2400 – Upgrade

Cables Supported:

341176-B21 SCSI Cable, VHDCI / Wide, 6 ft

341177-B21 SCSI Cable, VHDCI / Wide, 12 ft

201160-B21 SCSI Cable, VHDCI / Wide, 10 m

201160-B23*SCSI Cable, VHDCI / W, 20 m

328215-002 SCSI cable, Wide /Wide 10 m

328215-004 *SCSI cable, Wide /Wide 20 m

*Requires LVD SCSI extender 221249-B21

Check connectors on library and HBA/Router before ordering cables



Pre-sales site survey is required, document available on http://www.compaq.com/support/techpubs/installation_guides/146587-001.html

StorageWorks ESL9322S2 Library Configuration Guide

OS Supported

Windows NT 4.0, Windows 2000
Tru64 Unix 4.0G, 5.1 and 5.1A, (TruCluster)
Linux Redhat 7.1 and 7.2
SUSE Linux 7.2

ISV Software Applications Supported

VERITAS Backup Exec™ 8.6
CA BrightStor ARCserve2000™ for NT/2000
Legato NetWorker v6.1.2
VERITAS NetBackup v3.4.3, v4.5
CA BrightStor ARCserve/IT™ v7.0 for NetWare

Automation and Network Utilities Supported

HP Insight Manager
HP Tape Storage Management Console
MRU (Media robot utility)

For the ISV/OS support matrix refer to the Tape automation compatibility matrix on

<http://www.compaq.com/storage/tapelibrarymatrix.html>

Servers Supported

AlphaServer Systems:

AlphaServer GS320
AlphaServer GS160
AlphaServer GS80
AlphaServer ES45
AlphaServer ES40

ProLiant Servers:

ProLiant DL760
ProLiant ML750
ProLiant DL580/G2
ProLiant ML 570

Media/Label Supported

188527-B21 SDLT Media 5-Pack
188527-B22 SDLT Media 10-Pack
188527-B26 SDLT Media 20-Pack
158398-001 DLT Bar Code Labels
100 pieces



StorageWorks ESL9322S2 Library Configuration Guide

Standard Warranty: One year,
on-site next business day service

Installation SKUs

FM-E7INS-IN 309172-002 INSTALL
ESL9000 library 0-8 Drives

Capacity Upgrade Technology SKUs

293588-B21 ESL9322, slot upgrade 222 TO 322
slots*

*Serial number of your existing library is required
when ordering these capacity upgrade SKUs,

ESL9000 warranty upgrade options:

FM-E74HR-12	309164-002	1Y 9X5/4HR ESL 0-8 DR 1Y WAR
FM-E74HR-36	309165-002	3Y 9X5/4HR ESL 0-8 DR 1Y WAR
FM-E74HR-60	309166-002	5Y 9X5/4HR ESL 0-8 DR 1Y WAR
FM-E7724-12	309167-002	1Y 24X7/4HR ESL 0-8 DR 1Y WAR
FM-E7724-36	309168-002	3Y 24X7/4HR ESL 0-8 DR 1Y WAR
FM-E7724-60	309169-002	5Y 24X7/4HR ESL 0-8 DR 1Y WAR
FM-E7XHW-36	309170-002	3Y 9X5/ND ESL 0-8 DR 1Y WAR
FM-E7XHW-60	309171-002	5Y 9X5/ND ESL 0-8 DR 1Y WAR